

Fig. 1 is a cross-sectional view of a mechanical assembly. A central shaft (16) passes through several components. At the top, the shaft has a wavy section (30) and a smooth section (32). It is surrounded by a housing (10) which has a groove (12), a shoulder (13), and a flange (11). The shaft is secured at the bottom by a nut (8) and washer (14). Other labels include 1, 2, 2A, 2B, 3, 7, 17, 19, 20, 22, 26, 29, 31, and 33.

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11








FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17

